

Under Review Notification

Raised By: Scott Cameron

Product #: RBT400228M

Date: Oct 13 2017

Product Name: PSE, MAST NUT

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBT400228M-1	RBT400228M Rev 1	N	N	N	N	Y	N	N	17-706	Rework to new drawing

Description of Issue:
 RBT400228M-1 has counterbored clearance holes for 1/4"-20 socket cap screws around the inside bore
 Counterbores are too close to edge of material, leaving a paper thin wall of aluminum, which is cracking and reflects poor quality
 Drawing update will be released to remove the thin cracking material between counterbores and inside bore
 No functional impact to part
 Rework WIP and stock to new design.
 Required changes have already been communicated to Production, drawing release will formalize the change.

Distribution:

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------